ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar

Street ID	Street Name	Significant Landmark
W0093, W0024, W0042, W0040, W0099, W0046, W0050, W	15th Crs, NA, Om Shakthi Lyt 4th Crs	Varadarajanagara Gangamma Temple Road

Segment No.	Total Length (m)
11/C-W0093/S071250	227.96

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	64.99	77.542391	13.082169	77.542374	13.081582	RI-S56	W0050
2	45.06	77.543017	13.082564	77.543163	13.082183	RI-S56	W0046
3	117.91	77.543063	13.083856	77.542982	13.082793	W0024	RI-S56

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Road Construction of Culverts and Drains in Varadarajanagara Gangamma Temple Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Divi	1200000	2012

Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements to Road Construction of Culverts and Drains in Varadarajanagara Gangamma Temple Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-12-000036

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-TND/WO/116/2012-13	03/08/2012	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
03/08/2012	02/08/2013	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Scanned by CamScanner

S M VARADHARAJAPPA

Phone No.	E-Mail ID	0.00
9448734501		

Field Inspection Details

Number of Trees	Any Other Information	Name
4		RANGNATH
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0093, W0024, W0042, W0040,

Scanned by CamScanner

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	17/12/2016	16/01/2017	COMPLETED
SE	VASU K M	17/12/2016	16/01/2017	COMPLETED
EE	YARAPPA REDDY	17/12/2016	16/01/2017	COMPLETED
AEE	PRAKASH	17/12/2016	16/01/2017	COMPLETED
AE	RANGNATH	17/12/2016	16/01/2017	COMPLETED
AE	RANGNATH	17/12/2016	16/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0093, W0024, W0042, W0040,

Scanned by CamScanner